REMOVAL PROGRAM AFTER ACTION REPORT FOR THE PARK STREET SITE BENNINGTON, BENNINGTON COUNTY, VERMONT 17 SEPTEMBER 2012 THROUGH 12 JULY 2013

Prepared For:

U.S. Environmental Protection Agency Region I Emergency Planning and Response Branch 5 Post Office Square, Suite 100 Boston, Massachusetts 02109-3912

CONTRACT NO. EP-W-05-042

TDD NO. 01-12-08-0005

TASK NO. 0826

DC NO. R-7530

Submitted By:

Weston Solutions, Inc.
Superfund Technical Assessment and Response Team III (START)
3 Riverside Drive
Andover, Massachusetts 01810

September 2013

SDMS Doc ID 564859

HRS Reference #61 Page 1 of 45

TABLE OF CONTENTS

			<u>Page</u>
LIST	OF AP	PPENDICES	iii
1.0	INTF	RODUCTION	1
2.0	SITE	CONDITIONS AND BACKGROUND	1
	2.1	Site Location and Description	1
	2.2	Site History/Previous Actions	1
3.0	SUM	IMARY OF FEDERAL RESPONSE ACTIONS	2
	3.1	Organization of the Response	2
	3.2	Mobilization and Site Preparation	
	3.3	Chronology of Removal Activities	
4.0	ESTI	MATED COSTS OF THE REMOVAL ACTION	5
REFI	ERENC	ES	8

LIST OF APPENDICES

Appendix A Figures

Figure 1 - Site Location Map

Figure 2 - Site Diagram

Appendix B Photodocumentation Log

Appendix C Table 1 - Summary of Polychlorinated Biphenyl Results, Wipe Samples

iii

Collected in September 2012

1.0 <u>INTRODUCTION</u>

The following report, entitled *Removal Program After Action Report for the Park Street Site, Bennington, Bennington County, Vermont,* is a chronological summary of the response actions taken by the U.S. Environmental Protection Agency (EPA), Region I, Emergency Planning and Response Branch (EPRB). The report details the situation as it developed, actions taken, and resources committed

Site activities included: conducting particulate air monitoring and air sampling for polychlorinated biphenyls (PCBs); installing temporary lighting; performing decontamination of two residential basements including items located within the basements; removing and storing basement items in temporary storage containers; waterproofing the basements; and returning items back to their original place in the basements.

2.0 <u>SITE CONDITIONS AND BACKGROUND</u>

2.1 Site Location and Description

The Park Street site (the site) is located on Park Street and Bowen Road in Bennington, Bennington County, Vermont. Geographic coordinates of the site are 42° 53' 27.9" north latitude, and 73° 11' 32.9" west longitude, as measured from the approximate center of the site (see Appendix B, Figure 1). The site consists of Little League baseball fields, two residential properties, and adjacent wetlands. The site is adjacent to the former Jard Company, Inc. (JARD) site, and is abutted to the west by the Bennington Square Shopping Center, to the north by Bowen Road and industrial properties, to the east by the former JARD site, and to the south by the Roaring Branch of the Walloomsac River (Roaring Branch) (see Appendix C, Figure 2).

2.2 Site History/Previous Actions

The site has been impacted by contamination from the former JARD site, a former capacitor and transformer manufacturing facility that produced capacitors, non-fluid transformers, and motors used in household appliances. JARD generated wastes associated with its manufacturing processes from 1969 to 1986. These wastes included: PCBs; a variety of volatile organic compounds (VOCs), including trichloroethylene (TCE), 1,1,1-trichloroethane (1,1,1-TCA), and toluene; semivolatile organic compounds (SVOCs); waste hydraulic and lubricating oils; waste paints and varnishes; waste zinc oxide; waste-contaminated rejected capacitors; spent SpeediDriTM; and PCB- and phthalate-contaminated wastewater. From September 2006 through August 2007, U.S. EPA conducted a removal action at the JARD site, removing PCB-contaminated materials.

The Vermont Department of Environmental Conservation (VT DEC) raised concerns regarding surface and subsurface soil and groundwater contamination related to the site that is located down gradient of the former JARD site. Recent sampling by VT DEC has detected PCB's in groundwater at properties located near the former JARD property, which is suspected to be the source of the contamination. Groundwater levels near the site are approximately 5 to 8 feet below ground surface. Groundwater infiltration at residential homes located near the site has been identified as a potential source of PCB contamination to soils and surface waters at the properties.

On 2 through 5 April 2012, EPA and START personnel mobilized to the site to conduct sampling as part of a Preliminary Assessment/ Site Investigation (PA/SI). Personnel collected 104 surface and subsurface soil samples, 9 sediment samples, 6 surface water samples, and 4 floor sweeping samples from the site. All samples were screened on site for PCBs by the EPA Office of Environmental Measurement and evaluation (OEME) Mobile Laboratory. Approximately 10% of samples were also sent for laboratory confirmation PCB analysis at the OEME laboratory in North Chelmsford, Massachusetts (MA).

PCBs in the groundwater are suspected to be the source of contamination to soils and surface waters due to periodic infiltration into residential basements through inactive wells and other openings, and subsequent drainage via sumps and outfall pipes into yards and retention ponds. Analytical results of EPA samples of floor sweepings collected from the basement of a residential property detected PCBs at concentrations up to 14 ppm. PCBs were also detected in soils and surface water in a pond on a residential property, in the soil of sump areas located in the basements, in the soil at a nearby wetland, and in soil at the Little League field located along the JARD fence line.

3.0 <u>SUMMARY OF FEDERAL RESPONSE ACTIONS</u>

3.1 Organization of the Response

ORGANIZATION OF THE RESPONSE				
Organization	Representatives	Responsibilities		
U.S. Environmental Protection Agency (EPA) Emergency Planning and Response Branch (EPRB) 5 Post Office Square; Suite 100 Boston, MA 02109-3912 (617) 918-918-1052	Daniel Burgo	EPA On-Scene Coordinator (OSC) responsible for the initiation, oversight, and completion of all removal activities. The OSC coordinated with State and local officials.		
Weston Solutions, Inc. (Weston) Superfund Technical Assessment and Response Team (START) 3 Riverside Drive Andover, MA 01810 (978) 552-2107	Christine Scesny John Burton Kenneth Robinson	START Site Personnel that provided the OSC with technical assistance, site documentation, site health and safety monitoring, air monitoring, and draft and final report preparation.		
Environmental Restoration (ER) LLC 40 Messina Drive Braintree, MA 02184 (860) 769-7356	Christopher May Blake MacKinney	Response Manager (RM) for the ERRS contractor that performed removal activities. The RM was responsible for oversight and organization of mobilization, demobilization, and waste removal activities.		

3.2 Mobilization and Site Preparation

The site-specific removal health and safety plan (HASP) was reviewed and signed by all personnel before any work commenced. In addition, emergency telephone numbers and directions to the hospital were posted and work zones were delineated. All activities were performed in appropriate personal protective equipment (PPE) in accordance with the HASP. The HASP was prepared by START personnel as a separate document, entitled *Health and Safety Plan for the Park Street Site*, *Bennington, Bennington County, Vermont.* On 17 September 2012, the mobilization and staging of Emergency Rapid Response Services (ERRS) equipment was initiated.

Site preparation activities conducted by ERRS personnel consisted of reviewing and signing the Health and Safety Plan, mobilizing equipment and supplies, receiving delivery of supplies, and preparing a staging area.

3.3 Chronology of Removal Activities

Week of 23 July 2012

EPA Office of Site Remediation and Restoration (OSRR) Division Director James T. Owens III, signed the Action Memorandum approving the proposed removal action.

Week of 10 September 2012

On 12 September 2012, a site walk was conducted with the following personnel: EPA On-Scene Coordinator (OSC) Daniel Burgo, EPA OSC Eric Vanderboom, and ERRS Response Manager (RM) Chris May.

Activities for the day included:

- Reviewing and signing the HASP.
- Conducting a reconnaissance of the site property.

Week of 17 September 2012

Personnel on site:

OSC – EPA	Daniel Burgo
START – Weston Solutions, Inc.	Christine Scesny
ERRS Response Manager (RM) -	Christopher May
Environmental Restoration (ER)	
ERRS Crew – ER	1 foreman
	2 laborers

Equipment on site:

Type	Quantity
High Efficiency Particulate Air (HEPA)	3
Vacuum	
Truck	2
Storage Container	1
Portable Toilet	2
Dumpster	1
Handwash Station	1
5 KW Generator	1
55 Gallon Drum	2
Polyethylene (Poly) Sheeting	1
Poly Drum Liner	37
Lestoil®	4

Туре	Quantity
Negative Air Unit	1

Activities for the week included:

- Mobilizing the ERRS crew and equipment.
- Reviewing and signing the site HASP.
- Conducting air monitoring for particulates, Volatile Organic Compounds (VOCs), and explosive atmosphere as specified in the HASP.
- Decontaminating the basement areas and the items within the basements of P-001 and P-002 using a HEPA vacuum and Lestoil®.
- Returning all basement items back to their original locations after the decontamination activities had been completed.

On 22 September 2012, Northern Basement Systems representative Mike Doherty mobilized to the site to discuss the basement waterproofing of the two residential properties.

On 22 September 2012, decontamination activities had been completed and all personnel departed from the site. The basement waterproofing activities would be completed at a later date.

For the duration of the removal action, START photodocumented site activities (see Appendix B – Photodocumentation Log).

Week of 15 October 2012

On 17 October 2012, PCB air samples were collected by START to insure PCB contaminants had been removed during decontamination.

Activities for the day included:

- Reviewing and signing the HASP.
- Collecting air samples from the basement of (b) (6)

Week of 25 March 2013

Personnel on site:

OSC – EPA	Daniel Burgo
START – Weston	Christine Scesny
ERRS RM – ER	Christopher May
ERRS Crew – ER	2 laborers

Equipment on site:

Туре	Quantity
Truck	2
Portable Storage Unit	1
HEPA Vacuum	1
Portable Toilet	1

Activities for the week included:

- Mobilizing of the ERRS crew and equipment.
- Reviewing and signing the site HASP.
- Storing all items located in the basement of (b) (6) in a portable storage unit for the duration of basement waterproofing activities.
- Waterproofing the basements at (b) (6) to insure protection against PCB contamination via flooding.
- Installing a polyethylene liner on the basement walls, and installing an inner drain/French drain at the base of the walls at (b) (6).
- Installing a sump pump in the basement of (b) (6)

Key dates:

On 27 March 2013, EPA OSC Burgo, ERRS, and START member John Burton arrived on-site. The ERRS crew removed all of the property owners belongings from the basement at temporarily stored them in a portable storage unit.

On 27 and 28 March 2013, a Northern Basement System crew mobilized to site to conduct basement waterproofing activities at (b) (6)

On 28 February 2013, all personnel demobilized from the site.

Week of 13 May 2013

Personnel on site:

OSC – EPA	Daniel Burgo
START – Weston	Kenneth Robinson
ERRS RM	Christopher May
ERRS Crew – ER	2 laborers

Equipment on site:

Туре	Quantity
Truck	2
Portable Storage Unit	1
HEPA Vacuum	1
Portable Toilet	1

Activities for the week included:

- Mobilizing of crew and equipment.
- Review and signing of the site HASP.
- Storing all items located in the basement of (b) (6) in a portable storage unit for the duration of basement waterproofing activities.
- Waterproofing the basement at contamination via flooding. (b) (6) to insure protection against PCB contamination via flooding.

- Installing a poly liner on the basement walls, and installing an inner drain/French drain along the base of the walls at (b) (6).
- Installing a poly liner in a hallway leading from the bulkhead at (b) (6)
- Replacing all the basement items back to their original locations after the basement waterproofing activities were completed.

Key dates:

On 14 May 2013, EPA OSC Burgo, ERRS, and START member Robinson arrived on site. ERRS crew removed all of the property owners belongings from the basement at (b) (6) and temporarily stored them in a portable storage unit.

On 15 and 16 May 2013, Northern Basement System crew mobilized to site to conduct basement waterproofing activities at (b) (6)

On 17 May 2013, after the completion of the basement waterproofing activities ERRS crew returned all of the temporarily stored belongings back to the basements of (b) (6).

Week of 8 July 2013

Personnel on site:

OSC – EPA	Daniel Burgo
RM ERRS	Christopher May
ERRS Crew – ER	1 laborer

Key dates:

On 12 July 2013, ERRS mobilized to site to restore a section of the (b) (6) house siding.

On 12 July 2013, removal activities had been completed and all personnel demobilized from the site.

4.0 ESTIMATED COSTS OF THE REMOVAL ACTION

EPA resources committed under this Removal Action are summarized below:

Cost Category	Ceiling	Costs Incurred	Remainder	
Regional Removal Allowance Costs				
ERRS	\$500,000	\$ 81,379.54.	\$ 418,620.46	
Other Extramural Costs Not Funded from the Regional Allowance				
START Contractor \$250,000 \$35,201.00 \$214,			\$ 214,799.00	
Extramural Contingency	\$75,000	\$ 0.00	\$ 75,000.00	
Total Removal Project Costs	\$825,000	\$ 116,580.54	\$ 708,419.46	

This accounting of expenditures is an estimate based on figures known to the OSC at the time this report was written. The cost accounting provided in this report does not necessarily represent an exact monetary figure which the government may include in any claim for cost recovery.

REFERENCES

- [1] MicroPath U.S. Geological Survey (USGS). (7.5-minute series topographic) Quadrangle map: Bennington, Vermont.
- [2] Bing Maps Aerial. 2010. Microsoft Corporation, Available from http://www.bing.com. Internet accessed 23 March 2012.
- [4] Weston Solutions, Inc. START (Superfund Technical Assessment and Response Team). 2012. Field Logbook for the Park Street Site. TDD No. 12-03-0001.
- [5] Weston Solutions, Inc. START (Superfund Technical Assessment and Response Team). 2012. Removal Program Preliminary Assessment/Site Investigation Report for the Park Street Site, Bennington, Bennington County, Vermont, TDD No. 01-12-03-0002. September.
- [6] Weston Solutions, Inc. START (Superfund Technical Assessment and Response Team). 2013. Removal Program Preliminary Assessment/Site Investigation Report Addendum for the Park Street Site, Bennington, Bennington County, Vermont, TDD No. 01-12-03-0002. March.
- [7] Vista Analytical Laboratory. 2012. Vista Project I.D.:34073, Case 0847F, PUF Air Sample. 7 November.
- [8] U.S. Environmental Protection Agency. 2012. Office of Environmental Measurement and Evaluation. Laboratory Report. Project No. 12090038.Park Street Bennington, VT PCB's in Wipes. 15 October.

Appendices


HRS Reference #61 Page 12 of 45

Appendix A

Figures

Figure 1 - Site Location Map Figure 2 - Site Diagram

HRS Reference #61 Page 13 of 45






Figure 2

Site Diagram

Park Street Site Park Street Bennington, Vermont

EPA Region I Superfund Technical Assessment and Response Team (START) III Contract No. EP-W-05-042

TDD Number: 12-08-0005 Created by: E. Ackerman 23 March 2012 Created on: Modified by: Christine Scesny Modified on: 28 June 2013

Legend

Approximate Property Boundaries

Feet 125 250 0

Data Sources:

Imagery: Bing Maps Aerial (Microsoft Corp) All other data: START



The Trusted Integrator for Sustainable Solutions
Page 15 of 45

Appendix B

Photodocumentation Log

HRS Reference #61 Page 16 of 45



SCENE: View of a well located in the basement at (b) (6). Photograph was taken prior to decontamination.

DATE: 18 September 2012 TIME: 0759 hours **PHOTOGRAPHER:** Christine Scesny CAMERA: iPhone 4S



SCENE: View of the northern basement wall at (b) (6) prior to decontamination.

DATE: 18 September 2012 TIME: 0759 hours **PHOTOGRAPHER:** Christine Scesny **CAMERA:** iPhone 4S



SCENE: View of the northwestern basement walls at (b) (6) prior to decontamination.

DATE: 18 September 2012 TIME: 0800 hours **PHOTOGRAPHER:** Christine Scesny CAMERA: iPhone 4S



SCENE: View of a window located on the southern basement wall at (b) (6) prior to decontamination.

DATE: 18 September 2012 TIME: 0800 hours **PHOTOGRAPHER:** Christine Scesny CAMERA: iPhone 4S



SCENE: View of a basement wall at (b) (6) prior to decontamination.

DATE: 18 September 2012 TIME: 0800 hours **PHOTOGRAPHER:** Christine Scesny CAMERA: iPhone 4S



SCENE: View of the central and eastern area in the basement at (b) (6) prior to decontamination.

DATE: 18 September 2012 TIME: 0800 hours **PHOTOGRAPHER:** Christine Scesny **CAMERA:** iPhone 4



SCENE: View of a hall leading from the bulkhead door to the main basement at (b) (6). Wet areas are visible at the

base of the stone foundation wall.

DATE: 18 September 2012 TIME: 0801 hours **PHOTOGRAPHER:** Christine Scesny CAMERA: iPhone 4S



SCENE: View of the negative air system used during decontamination operations at (b) (6)

DATE: 18 September 2012 TIME: 1321 hours **PHOTOGRAPHER:** Christine Scesny **CAMERA:** iPhone 4S



SCENE: View of the location of particulate air monitor number (No.) 2 at (b) (6) Photograph taken facing north.

DATE: 19 September 2012 TIME: 0806 hours **PHOTOGRAPHER:** Christine Scesny CAMERA: iPhone 4S



SCENE: View of the location of particulate air monitor No. 1 at (b) (6) Photograph taken facing northwest.

DATE: 19 September 2012 TIME: 0807 hours **PHOTOGRAPHER:** Christine Scesny CAMERA: iPhone 4S



SCENE: View of the negative air system set up at (b) (6) during decontamination activities.

DATE: 20 September 2012 TIME: 0813 hours **PHOTOGRAPHER:** Christine Scesny CAMERA: iPhone 4S



SCENE: View of the western central basement area at (b) (6) prior to decontamination.

DATE: 20 September 2012 TIME: 0814 hours **PHOTOGRAPHER:** Christine Scesny **CAMERA:** iPhone 4S



SCENE: View of the southeastern basement area at (b) (6) prior to decontamination. Water is visible on the floors.

DATE: 20 September 2012 TIME: 0814 hours **PHOTOGRAPHER:** Christine Scesny CAMERA: iPhone 4S



SCENE: View of the central basement area located behind the stairwell at (b) (6). The photograph was taken prior to decontamination activities.

DATE: 20 September 2012 TIME: 0815 hours **PHOTOGRAPHER:** Christine Scesny **CAMERA:** iPhone 4S



SCENE: View of a hole in the northern basement wall at

decontamination.

DATE: 20 September 2012 PHOTOGRAPHER: Christine Scesny

(b) (6)

. The photograph was taken prior to

TIME: 0818 hours **CAMERA:** iPhone 4S



SCENE: View of the northeastern basement area at **(b) (6)** prior to decontamination.

DATE: 20 September 2012

PHOTOGRAPHER: Christine Scesny

TIME: 0818 hours **CAMERA:** iPhone 4S



SCENE: View of the location of particulate air monitor No. 2 at (b) (6) Photograph taken facing south.

DATE: 20 September 2012 TIME: 0820 hours **PHOTOGRAPHER:** Christine Scesny CAMERA: iPhone 4S



SCENE: View of the location of particulate air monitor No. 1 at (b) (6) Photograph taken facing northeast.

DATE: 20 September 2012 TIME: 0821 hours **PHOTOGRAPHER:** Christine Scesny CAMERA: iPhone 4S



SCENE: View of northwestern basement area at (b) (6) following decontamination.

DATE: 22 September 2012 PHOTOGRAPHER: Christine Scesny TIME: 0913 hours **CAMERA:** iPhone 4S



SCENE: View of wipe sample location WS-01 at

(b) (6) . The sample was collected following decontamination.

DATE: 22 September 2012

PHOTOGRAPHER: Christine Scesny

TIME: 1017 hours **CAMERA:** iPhone 4S



SCENE: View of wipe sample location WS-02 (Duplicate WS-03) at (b) (6) The photograph was taken following

decontamination.

DATE: 22 September 2012 PHOTOGRAPHER: Christine Scesny

TIME: 1022 hours **CAMERA:** iPhone 4S



SCENE: View of wipe sample location WS-04 at (b) (6). The photograph was taken following decontamination.

DATE: 22 September 2012 TIME: 1025 hours PHOTOGRAPHER: Christine Scesny **CAMERA:** iPhone 4S




SCENE: View of the northeastern basement area at (b) (6) following decontamination.

DATE: 22 September 2012 TIME: 1029 hours **PHOTOGRAPHER:** Christine Scesny CAMERA: iPhone 4S



SCENE: View of wipe sample locations WS-06 and WS-07 collected from the freezer doors at photograph was taken following decontamination.

DATE: 22 September 2012 TIME: 1118 hours **PHOTOGRAPHER:** Christine Scesny CAMERA: iPhone 4S



SCENE: View of wipe sample locations WS-08, WS-09, and WS-10 at (b) (6). The samples were collected from the furnace, washing machine, and the drying machine, respectively. The photograph was taken following decontamination.

DATE: 22 September 2012 TIME: 1119 hours **PHOTOGRAPHER:** Christine Scesny CAMERA: iPhone 4S



SCENE: View of stored materials in the eastern portion of the basement of (b) (6). Photograph taken facing east.

DATE: 14 May 2013 TIME: 1005 hours **PHOTOGRAPHER:** Kenneth Robinson CAMERA: iPhone 4S



SCENE: View of stored materials in the western portion of the basement of (b) (6). Photograph taken facing

southwest.

DATE: 14 May 2013 TIME: 1300 hours **PHOTOGRAPHER:** Kenneth Robinson **CAMERA:** iPhone 4S



SCENE: View of the portable storage unit at (b) (6) . Photograph taken facing south.

DATE: 14 May 2013 **TIME:** 1439 hours **PHOTOGRAPHER:** Kenneth Robinson **CAMERA:** iPhone 4S



SCENE: View of suspected effluent piping from the former sump pump system of (b) (6). Photograph taken facing

south.

DATE: 14 May 2013 TIME: 1443 hours **PHOTOGRAPHER:** Kenneth Robinson **CAMERA:** iPhone 4S



SCENE: View of the woodpile that was removed from the basement and stacked outside (b) (6). Photograph taken

facing west.

DATE: 14 May 2013 TIME: 1446 hours **PHOTOGRAPHER:** Kenneth Robinson CAMERA: iPhone 4S



SCENE: View of polyethylene (poly) sheeting over stored materials and remaining materials removed in the basement of

(b) (6) . Photograph taken facing west.

DATE: 14 May 2013 TIME: 1537 hours
PHOTOGRAPHER: Kenneth Robinson CAMERA: iPhone 4S



SCENE: View of temporary stairs on top of the poly liner in the (b) (6) basement. Photograph taken facing north.

DATE: 15 May 2013 TIME: 0858 hours **PHOTOGRAPHER:** Kenneth Robinson **CAMERA:** iPhone 4S



SCENE: View of stored materials staged on top of the poly liner in the (b) (6) basement.

DATE: 15 May 2013 TIME: 0858 hours **PHOTOGRAPHER:** Kenneth Robinson **CAMERA:** iPhone 4S



SCENE: View of the poly liner on the wall and the French drain system in (b) (6) basement.

DATE: 15 May 2013 TIME: 0858 hours **PHOTOGRAPHER:** Kenneth Robinson **CAMERA:** iPhone 4S



SCENE: View of stored materials and the furnace area of the (b) (6) basement after the installation of poly liner and a French drain system. Photograph taken facing east.

DATE: 15 May 2013 TIME: 0859 hours PHOTOGRAPHER: Kenneth Robinson **CAMERA:** iPhone 4S



SCENE: View of the sump pump system and poly sheeting installed in the northwest corner of the basement of (b) (6)

. Photograph taken facing west.

DATE: 15 May 2013 TIME: 0900 hours PHOTOGRAPHER: Kenneth Robinson **CAMERA:** iPhone 4S

TDD-129-Reference 451 Page 18 of 26 F-26-SK4 N/04-50826



SCENE: View of the aboveground storage tank (AST) that was staged on a crushed gravel platform after the installation of a poly liner and French Drain system in the basement of (b) (6).

DATE: 15 May 2013 TIME: 0901 hours PHOTOGRAPHER: Kenneth Robinson **CAMERA:** iPhone 4S



SCENE: View of effluent piping from the

taken facing southeast. **DATE:** 15 May 2013

TDD-129-Reference 451

PHOTOGRAPHER: Kenneth Robinson

(b) (6) sump pump system prior to subsurface installation. Photograph

TIME: 0907 hours **CAMERA:** iPhone 4S


> Page 19 of 26 $F_{ab} = 1000$



SCENE: View of suspected location of sanitary sewer piping as marked by the homeowner at (b) (6). Photograph

taken facing south. **DATE:** 15 May 2013 PHOTOGRAPHER: Kenneth Robinson

TIME: 0907 hours **CAMERA:** iPhone 4S



TOP

SCENE: View of the basement of (b) (6) after the installation of a poly liner and French drain system. Photograph

taken facing west.

DATE: 17 May 2013

PHOTOGRAPHER: Dan Burgo

TIME: 1521 hours

CAMERA: Cannon PowerShot



TOP

SCENE: View of the basement of

(b) (6)

after the installation of a poly liner and French drain system. Photograph

taken facing southwest. **DATE:** 17 May 2013

PHOTOGRAPHER: Dan Burgo

TIME: 1521 hours

CAMERA: Cannon PowerShot



TOP

SCENE: View of the basement of (b) (6) after the installation of a poly liner and French drain system. Visible in the background is the AST on a crushed gravel platform. Photograph taken facing west.

DATE: 17 May 2013 **TIME:** 1522 hours

PHOTOGRAPHER: Dan Burgo CAMERA: Cannon PowerShot



SCENE: View of the basement of

(b) (6) after the installation of a poly liner and French Drain system. Photograph

taken facing south. **DATE:** 17 May 2013

PHOTOGRAPHER: Dan Burgo

TIME: 1522 hours

CAMERA: Cannon PowerShot



SCENE: View of a grate drain installed in the basement of (b) (6). The grate is located along the outside entryway

to the basement.

DATE: 17 May 2013

PHOTOGRAPHER: Dan Burgo

TIME: 0521 hours

CAMERA: Cannon PowerShot



SCENE: View of a small drainage cover to the drainage pipe installed in the yard of (b) (6)

DATE: 17 May 2013 **TIME:** 1520 hours

PHOTOGRAPHER: Dan Burgo CAMERA: Cannon PowerShot



TOP

SCENE: View of the sump pump system installed in the basement of (b) (6). Photograph taken facing west.

DATE: 20 May 2013 **TIME:** 1747 hours

PHOTOGRAPHER: Dan Burgo CAMERA: Cannon PowerShot



SCENE View of the sump pump system installed in the basement of (b) (6). Photograph taken facing west.

DATE: 20 May 2013 **TIME:** 1746 hours

PHOTOGRAPHER: Dan Burgo **CAMERA:** Cannon PowerShot



TOP

TOP

SCENE: View of effluent piping from the sump pump system from the

(b) (6) basement. Photograph taken facing

east.

DATE: 17 May 2013 TIME: 1521 hours

PHOTOGRAPHER: Dan Burgo CAMERA: Cannon PowerShot

TDD-129-Reference 451 Page 24 of 26 FLASKO NO450826



SCENE: View of effluent piping from the sub-slab venting/pumping system from the (b) (6) basement. Photograph

taken facing south.

DATE: 12 July 2013 TIME: 1117 hours **PHOTOGRAPHER:** Dan Burgo CAMERA: iPhone 5



SCENE: View of effluent piping from the sub-slab venting/pumping system from the (b) (6) basement. Photograph

taken facing south.

DATE: 12 July 2013 TIME: 1118 hours **PHOTOGRAPHER:** Dan Burgo CAMERA: iPhone 5



SCENE: View of repaired vinyl siding around a water spigot at (b) (6). Photograph taken facing south.

DATE: 12 July 2013 TIME: 1118 hours **PHOTOGRAPHER:** Dan Burgo CAMERA: iPhone 5



SCENE: View of repaired vinyl siding around a water spigot at (b) (6). Photograph taken facing south.

DATE: 12 July 2013 TIME: 1118 hours **PHOTOGRAPHER:** Dan Burgo CAMERA: iPhone 5

Appendix C

Table 1 – Summary of Polychlorinated Biphenyl Results, Wipe Samples Collected in September 2012

HRS Reference #61 Page 43 of 45

TABLE 1

SUMMARY OF POLYCHLORINATED BIPHENYL RESULTS WIPE SAMPLES COLLECTED IN SEPTEMBER 2012 PARK STREET SITE BENNINGTON, VERMONT

SAMPLE LOCATION SAMPLE NUMBER SAMPLE DATE SAMPLE SURFACE	WS-01 R01-120917DB-0001 9/22/2012 WATER HEATER (b) (6)	WS-02 R01-120917DB-0002 9/22/2012 COAL STOVE (b) (6)	WS-03 R01-120917DB-0003 9/22/2012 COAL STOVE (b) (6)	WS-04 R01-120917DB-0004 9/22/2012 FURNACE (b) (6)
COMPOUND				
Aroclor-1016	ND	ND	ND	ND
Aroclor-1221	ND	ND	ND	ND
Aroclor-1232	ND	ND	ND	ND
Aroclor-1242	ND	ND	ND	ND
Aroclor-1248	ND	ND	ND	ND
Aroclor-1254	ND	ND	ND	ND
Aroclor-1260	ND	ND	ND	ND
Aroclor-1262	ND	ND	ND	ND
Aroclor-1268	ND	ND	ND	ND

SAMPLE LOCATION SAMPLE NUMBER SAMPLE DATE SAMPLE SURFACE	R01-120917DB-0005 9/22/2012	WS-06 R01-120917DB-0006 9/22/2012 FREEZER-01 (b) (6)	WS-07 R01-120917DB-0007 9/22/2012 FREEZER-02 (b) (6)	WS-08 R01-120917DB-0008 9/22/2012 FURNACE (b) (6)
COMPOUND				
Aroclor-1016	ND	ND	ND	ND
Aroclor-1221	ND	ND	ND	ND
Aroclor-1232	ND	ND	ND	ND
Aroclor-1242	ND	ND	ND	ND
Aroclor-1248	ND	ND	ND	ND
Aroclor-1254	ND	ND	ND	ND
Aroclor-1260	ND	ND	ND	ND
Aroclor-1262	ND	ND	ND	ND
Aroclor-1268	ND	ND	ND	ND

NOTES:

- 1) Samples analyzed by U.S. EPA Office of Environmental Measurement and Evaluation (OEME) using EPA Region I SOP, EIA:SOP-PCBWIPE1.SOP, PCBs in wipe sample.
- 2) All Results in Micrograms per wipe (µg/wipe).
- 3) ND = Not Detected.
- 4) Each wipe sample was collected over a non-porous surface area of 100 centimeters (cm) and preserved in 10 milliliters (ml) of Hexane.

TABLE 1

SUMMARY OF POLYCHLORINATED BIPHENYL RESULTS WIPE SAMPLES COLLECTED IN SEPTEMBER 2012 PARK STREET SITE BENNINGTON, VERMONT

SAMPLE LOCATION SAMPLE NUMBER SAMPLE DATE SAMPLE SURFACE	R01-120917DB-0009 9/22/2012	WS-10 R01-120917DB-0010 9/22/2012 DRYING MACHINE (b) (6)	
COMPOUND			
Aroclor-1016	ND	ND	
Aroclor-1221	ND	ND	
Aroclor-1232	ND	ND	
Aroclor-1242	ND	ND	
Aroclor-1248	ND	ND	
Aroclor-1254	ND	ND	
Aroclor-1260	ND	ND	
Aroclor-1262	ND	ND	
Aroclor-1268	ND	ND	

NOTES:

- 1) Samples analyzed by U.S. EPA Office of Environmental Measurement and Evaluation (OEME) using EPA Region I SOP, EIA:SOP-PCBWIPE1.SOP, PCBs in wipe sample.
- 2) All Results in Micrograms per wipe (µg/wipe).
- 3) ND = Not Detected.
- 4) Each wipe sample was collected over a non-porous surface area of 100 centimeters (cm) and preserved in 10 milliliters (ml) of Hexane.